

OZNAKE PROFILOV	P_A-0	P_A-1	P_A-2	P_A-3	P_A-4	P_A-5	P_A-6	P_A-7	
STACIONAŽE	0.29	10.04	26.72	43.02	57.30	78.24	92.96	0.1	9.28
KOTE TERENA	195.448	195.595	195.932	196.320	197.136	198.199	198.379	197.480	
KOTE NIVELETE	195.448	195.589	195.988	196.315	196.460	196.705	197.069	197.480	
PREME IN KRIVINE									
PREČNI NAGIBI									

